UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

l.	OCCURRED STRUCTURAL DAMAGE
	DATE: 14-MAR-2021 TIME: 1050 HOURS X CRANE
2.	OPERATOR: Cox Operating, L.L.C. OTHER LIFTING DAMAGED/DISABLED SAFETY SYS
•	DAMAGED/DISABLED SAFETY SYS. REPRESENTATIVE: INCIDENT >\$25K
	TELEPHONE: H2S/15MIN./20PPM
	CONTRACTOR: REQUIRED MUSTER
	REPRESENTATIVE: SHUTDOWN FROM GAS RELEASE
	TELEPHONE: OTHER
3	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR 8. OPERATION:
•	ON SITE AT TIME OF INCIDENT:
	x PRODUCTION
1.	LEASE: G01870 DRILLING
	AREA: ST LATITUDE: WORKOVER COMPLETION
	BLOCK: 26 LONGITUDE: HELICOPTER
	MOTOR VESSEL
5.	PLATFORM: D-QTRS PIPELINE SEGMENT NO.
	RIG NAME:
5.	ACTIVITY: EXPLORATION(POE) X DEVELOPMENT/PRODUCTION 9. CAUSE:
7.	(DOCD/POD) TYPE:
	INJURIES: EQUIPMENT FAILURE
	HISTORIC INJURY X HUMAN ERROR EXTERNAL DAMAGE
	OPERATOR CONTRACTOR SLIP/TRIP/FALL
	REQUIRED EVACUATION WEATHER RELATED
	LTA (1-3 days)
	LTA (>3 days) RW/JT (1-3 days) UPSET H20 TREATING OVERBOARD DRILLING FLUID
	RW/JT (>3 days) OTHER
	FATALITY
	Other Injury 10. WATER DEPTH: 53 FT.
	11. DISTANCE FROM SHORE: 7 MI.
	POLLUTION 13 HIND DIRECTION:
	FIRE 12. WIND DIRECTION: SPEED: M.P.H.
	EXPLOSION SPEED: M.P.H.
	LWC HISTORIC BLOWOUT 13. CURRENT DIRECTION:
	UNDERGROUND SPEED: M.P.H.
	SURFACE
	DEVERTER 14. SEA STATE: FT.
	SURFACE EQUIPMENT FAILURE OR PROCEDURES 15. PICTURES TAKEN:
	COLLISION HISTORIC >\$25K <=\$25K 16. STATEMENT TAKEN:

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R 22-JUL-2021

On March 14, 2021, at approximately 0800 the crew of ST 26 CDF was attempting to offload the Motor Vessel "Captain Rod" when high strain of the aux line occurred. The Crane Operator of the ST 26 D crane latched onto the load which had been manifested from the boat dock to weigh 4,300 lbs. However, when the lift was made, the crane reportedly "struggled and bogged down". After further investigation it was determined that the actual load weight was 8,500 lbs instead of the labeled weight of 4,300 lbs.

BSEE Houma District investigation found that the cause of this incident is determined to be poor communication between the dock crane operator and the dispatcher. Normal operations to manifest the weight of a load at the dock is for the Crane Operator to call out the weight as indicated on the load indicator while loading the boat to the Dispatcher who records it on the manifest. According to witness statements, the Crane Operator called out 8,500 lbs, but the Dispatcher recorded the incorrect weight of 4,300 lbs.

The load chart for the aux line for the crane on ST 26 D shows it is rated for 6,650 lbs at all angles during both dynamic and static lifts. The aux cable certificate for the crane on ST 26 D reflect a rating of 45,000 lbs. The winch certification reflects a rating of 12,000 lbs. According to the Sparrow Crane Engineer, it is determined that the weak point of the crane is the jib bolts that connect the jib to the crane boom. However, after the incident, an inspection of the crane was conducted, and no damage was noted to the jib assembly.

BSEE Houma District Office cannot determine the exact cause of the damage found to the aux line cable. The aux line cable and winch were both rated for more than the weight of the load. However, it is noted that the last annual inspection was completed on May 29, 2020, approximately 10 months before the incident occurred in March 2021. The crane was due for its next annual inspection on May 29, 2021.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Poor communication between the dock crane operator and the dispatcher caused the basket weight to be mislabeled.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

None

20. LIST THE ADDITIONAL INFORMATION:

N/a

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

Crane Aux Line Cable

High strain on crane aux cable

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Houma District has no reccomendations for OII about this incident.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

N/A

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R 22-JUL-2021

25. DATE OF ONSITE INVESTIGATION:

03-MAR-2021

26. INVESTIGATION TEAM MEMBERS:
 Francis Gary / Bruce Crabtree /

27. OPERATOR REPORT ON FILE:

28. ACCIDENT CLASSIFICATION:

For Public Release

29. ACCIDENT INVESTIGATION PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR: Amy

Pellegrin

APPROVED

DATE: 01-JUN-2021

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R 22-JUL-2021