UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

1.	OCCURRED ST	IRUCTURAL DAMAGE
		RANE
2.	OPERATOR:Cox Operating, L.L.C.DAREPRESENTATIVE:INTELEPHONE:H12CONTRACTOR:W-IndustriesREPRESENTATIVE:SH	THER LIFTING AMAGED/DISABLED SAFETY SYS. NCIDENT >\$25K 2S/15MIN./20PPM EQUIRED MUSTER HUTDOWN FROM GAS RELEASE THER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	
	LEASE: 00026 AREA: WD LATITUDE: BLOCK: 30 LONGITUDE: PLATFORM: T	X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL
5.	RIG NAME:	DIPELINE SEGMENT NO.
6.	ACTIVITY: EXPLORATION (POE) DEVELOPMENT/PRODUCTION (DOCD/POD)	9. CAUSE:
7.	TYPE: INJURIES: HISTORIC INJURY OPERATOR CONTRACTOR X REQUIRED EVACUATION 0 1 LTA (1-3 days) LTA (>3 days) RW/JT (1-3 days) RW/JT (>3 days)	R EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	FATALITY	10. WATER DEPTH: 50 FT.
	X Other Injury 0 1 Medical Recordable	11. DISTANCE FROM SHORE: 8 MI.
	POLLUTION FIRE EXPLOSION	12. WIND DIRECTION: SPEED: M.P.H.
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE	13. CURRENT DIRECTION: SPEED: M.P.H.
	DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	14. SEA STATE: FT. 15. PICTURES TAKEN:
	COLLISION HISTORIC >\$25K <-=\$25K	16. STATEMENT TAKEN:

17. INVESTIGATION FINDINGS:

INCIDENT SUMMARY:

On 26 September 2021, an injury occurred on West Delta (WD) 30 T, a production platform owned and operated by Cox Operating, LLC. An Instrumentation & Electrical (I&E) Tech contracted with W-Industries was working on removing damaged tubing from a well panel when the door swung open and injured the I&E tech's index finger, causing a laceration that would require treatment beyond first aid. The Injured Person (IP) was flown to an onshore medical facility shortly after the incident occurred where the IP was treated and released back to duty the same day on 26 September 2021.

SEQUENCE OF EVENTS:

On 26 September 2021 at approximately 0930 hours, the IP was removing damaged tubing from a well panel when the panel door swung open and pinched the IP's right index finger between the side of the panel and door hinge, causing a laceration. The IP was treated with first aid on site before being flown to an Hospital where treatment beyond first aid was given. The IP was released back to duty following treatment received at the hospital on 26 September 2021.

BSEE INVESTIGATION:

27 September 2021, Bureau of Safety and Environmental Enforcement (BSEE) Accident Investigator (AI) received an email with a brief summary of the incident.

28 September 2021, the AI obtained documents and photographs from the incident and what treatment the IP received.

CONCLUSIONS:

While the IP was working on removing damaged tubing from the inside of the panel, wind caught the well panel door causing it to swing open and pinch the IP's finger between the side of the panel and door panel hinge. The IP was wearing impact gloves consisting of Nylon and Spandex with a Nitrile Butadiene Rubber (NBR) coating. This glove has high dexterity, but scores low in cut, tear, and puncture resistance.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

• Human Performance Error - Inattention to task: Personnel failed to secure panel door.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

• Work Environment - No or impropper PPE: IP's gloves did not provide adequate protection from edges or impact.

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

26. INVESTIGATION TEAM MEMBERS:

27. OPERATOR REPORT ON FILE:

Nathan Bradley /

- 28. ACCIDENT CLASSIFICATION:
 - 29. ACCIDENT INVESTIGATION PANEL FORMED: NO OCS REPORT:
- 30. DISTRICT SUPERVISOR: David Trocquet

APPROVED DATE: 09-JAN-2022

MMS - FORM 2010