

UNITED STATES DEPARTMENT OF THE INTERIOR
MINERALS MANAGEMENT SERVICE
GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1. OCCURRED

DATE: **12-NOV-2006** TIME: **0700** HOURS

2. OPERATOR: **Newfield Exploration Company**

REPRESENTATIVE: **Gary Harrington**

TELEPHONE: **(281) 847-6090**

CONTRACTOR: **ISLAND OPERATORS CO. INC.**

REPRESENTATIVE: **Jason Veillion**

TELEPHONE: **(337) 232-2416**

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR
ON SITE AT TIME OF INCIDENT:

4. LEASE: **G04090**

AREA: **WC** LATITUDE:

BLOCK: **294** LONGITUDE:

5. PLATFORM: **C**

RIG NAME:

6. ACTIVITY: ☐ EXPLORATION(POE)
☒ DEVELOPMENT/PRODUCTION
(DOCD/POD)

7. TYPE:

☐ HISTORIC INJURY

☐ REQUIRED EVACUATION

☐ LTA (1-3 days)

☐ LTA (>3 days)

☐ RW/JT (1-3 days)

☐ RW/JT (>3 days)

☐ Other Injury

☐ FATALITY

☐ POLLUTION

☐ FIRE

☒ EXPLOSION

LWC

☐ HISTORIC BLOWOUT

☐ UNDERGROUND

☐ SURFACE

☐ DEVERTER

☐ SURFACE EQUIPMENT FAILURE OR PROCEDURES

COLLISION ☐ HISTORIC ☐ >\$25K ☐ <=\$25K

☐ STRUCTURAL DAMAGE

☐ CRANE

☐ OTHER LIFTING DEVICE

☐ DAMAGED/DISABLED SAFETY SYS.

☒ INCIDENT >\$25K **pipeline and structural**

☐ H2S/15MIN./20PPM **damage**

☐ REQUIRED MUSTER

☐ SHUTDOWN FROM GAS RELEASE

☐ OTHER

6. OPERATION:

☐ PRODUCTION

☐ DRILLING

☐ WORKOVER

☐ COMPLETION

☐ HELICOPTER

☐ MOTOR VESSEL

☒ PIPELINE SEGMENT NO. **13162**

☐ OTHER

8. CAUSE:

☐ EQUIPMENT FAILURE

☐ HUMAN ERROR

☒ EXTERNAL DAMAGE

☐ SLIP/TRIP/FALL

☐ WEATHER RELATED

☐ LEAK

☐ UPSET H2O TREATING

☐ OVERBOARD DRILLING FLUID

☐ OTHER

9. WATER DEPTH: **44** FT.

10. DISTANCE FROM SHORE: **30** MI.

11. WIND DIRECTION:
SPEED: M.P.H.

12. CURRENT DIRECTION:
SPEED: M.P.H.

13. SEA STATE: FT.

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

Operator stated they were preparing to shut-in the WC294 A structure for hot work and they went to Scada onboard 294A and remotely shut-in well C-2 on 294C prior to shutting in the SDV on WC294A host facility. Operator states they were unaware that the 294C2 well did not shut. Stated the PSH 1 and 2 failed. They also heard then observed a large amount of gas vapors escaping to the atmosphere from what they believed to be the PSV on the fuel gas system. Upon arrival at WC-294-C it was discovered that the departing pipeline had parted. The investigation revealed that fragments from the rupture of the pipeline riser damaged the pneumatic boat loop ESD, which shut-in the C-2 well. This ESD system is separate from that of the remote ESD system.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Operators failed to follow proper steps for total shut-in of entire field and host facility. Operator failed to recognize critical warning signs indicated on the Scada log, PSH1 AND PSH2 tripped and operator acknowledged but no mitigating action was taken to prevent the pipeline from overpressure. The panel at WC-294-C was not properly designed and prevented the safety devices from performing their design function. (PSH-1&2 S/D signals were not connected to independent solenoids, so if this single solenoid failed then neither PSH would perform its function).

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Operator failed to verify closure of well C2 at WC294C before initiating closure of the incoming pipeline SDV at WC294A. Operator not being familiar with all aspects of the Scada system allowed critical warning signs to be overlooked. The operators had no detailed written procedure to follow for shutting in the entire field including the host facility. Operations personnel relied on the cascading affect to initiate shut-in action of the satellite wells.

21. PROPERTY DAMAGED:

Pipeline segment 13162, Navajids
Equipment, small materials, pipeline
braces.

NATURE OF DAMAGE:

Pipeline parted in two. Braces broken off.
Navajids equipment missing or damaged.

ESTIMATED AMOUNT (TOTAL):

\$100,000

22. RECOMMENDATIONS TO PREVENT RECCURANCE NARRATIVE:

The Lake Charles District recommends that a Safety Alert be issued with the following recommendations. For pipelines that deliver production to a host facility and you are subject to pressure greater than the MAOP encourage operators that have Scada systems installed on both the satellite and host facility to install a valve position indicator on the incoming SDV, which sends a shut-down signal to close all affected wells when the incoming SDV on the host facility closes. Furthermore, for a scheduled shut in, verify that all production from satellite structures is shut in at the wellhead prior to closure of the incoming SDV at the host platform.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

G-110 Operator failed to perform annual function test on production safety system as per 14C appendix D.

p-405 Well C-2 has a SITP greater than the flowline/pipeline MAOP and does not have an independent PSH or PSV.

G-110 The operator failed to perform operations in a safe and workmanlike manner.

- * The JSA which was provided to MMS was deficient in terms of detail.

- * The failure to utilize Apache's "STOP" work authority policy allowed critical warning signs to be over looked.

- * A written detailed procedure for shutting in the entire field including WC-294-A was not followed.

25. DATE OF ONSITE INVESTIGATION:

14-NOV-2006

26. ONSITE TEAM MEMBERS:

Wayne Meaux / Guy Thibodeaux /
Scott Mouton / Ricky Deville /

29. ACCIDENT INVESTIGATION

PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

F Pausina for L Williamson

APPROVED

DATE: 31-JAN-2007