Revised Permit to Modify (RPM)

Lease P00166 Area LA	A Block 6660 Well Name	A030 ST 00 BP 00 Type Development
Application Status App	proved Operator 01560	Pacific Operators Offshore, LLC
Pay.gov Amount:	Agency Tracking ID:	Pay.gov Tracking ID:
General Informatio	n	
API 043112007100	Approval Dt 15-MAR-2	Approved By John Kaiser
Submitted Dt 06-MAR-20	17 Well Status Complete	ed Water Depth 154
Surface Lease P00166	Area LA	Block 6660

Approval Comments

COAs:

- 1- Notify the Permitting Section at least 24 hours in advance of beginning these approved operations AND of any required BOP Tests.
- 2- Notify the Permitting Section at least 24 hours in advance of any cement plug pressure test or tagging.
- 3- WAR reports are due by 1200 on Wednesday following the week of report.

Correction Narrative

The existing perforations were isolated with a retainer and capped with cement as per original program.

An attempt was made to cut the 7" casing at 1472' but was unable to circulate water to surface. The pressure built up to 500 psi and held. A second attempt was made to cut the casing shallower at 1200' but again circulation with water failed. It pressured up to 400 psi and held.

The revision program calls for perforating at 800', establish circulation then cut and recover the 7" casing. If circulation is not established, then perforate at 550' and establish circulation prior to pulling and cutting casing. Finally, the program has provisions to temporarily abandon the well if no circulation is established.

Permit Primary Type Abandonment Of Well Bore

Permit Subtype(s)

Temporary Abandonment

Operation Description

Procedural Narrative

The rig moved on the well on 2/9/2017 and all Gas Lift Equipment was recovered. Set a retainer at 3150' (96' above the perf's)but was unable to establish pumping rate. Spotted cement above retainer with TOC at 3010', and filled hole with abandonment mud to first casing cut at 1472'. Cut 7" casing but unable to circulate and pull casing. Moved up to 1200' and made a second cut but could not establish circulation or pull casing. Moved rig off well for further instructions.

This RPM calls for setting a plug across the failed casing cuts, perforating the 7" casing shallower to establish circulation, cut and retrieve the casing. The program also has provisions for proper casing abandonment with retainers and cement plugs in case circulation is not established..

Finally, a BP will be set at 500' ORKB and 150' of abandonment cement will be spotted above.

Page:

1

of

4

Revised Permit to Modify (RPM)

Lease P00166 Area LA Block 6660 Well Name A030 ST 00 BP 00 Type Development

Application Status Approved Operator 01560 Pacific Operators Offshore, LLC

Note: Recovery of the remaining casing strings down to 15' below the mud line will be done at the time of permanent abandonment.

Subsurface Safety Valve

Type Installed SSCSV

Feet below Mudline 121

Maximum Anticipated Surface Pressure (psi) 160

Shut-In Tubing Pressure (psi) 135

Rig Information

Name	Id	Type	ABS Date	Coast Guard Date
* PLATFORM RIG TO BE DETERMINI	60006	PLATFORM	31-DEC-2019	31-DEC-2019

Blowout Preventers	Test Pressure				
Preventer	Size	Working Pressure	Low	High	
Annular		3000	250	750	
Rams	12	3000	250	750	

Date Commencing Work (mm/dd/yyyy) 10-APR-2017

Estimated duration of the operation (days) 7

Verbal Approval Information

Official Date (mm/dd/yyyy)

Questions						
~	Number Question Response Response Text					
1	Is H2S present in the well? If yes, then comment on the inclusion of a Contingency Plan for this operation.	NO	Response Text			
2	Is this proposed operation the only lease holding activity for the subject lease? If yes, then comment.	NO				
3	Will all wells in the well bay and related production equipment be shut-in when moving on to or off of an offshore platform, or from well to well on the platform? If not, please explain.	NO	Rig moves on a skid frame on an upper deck above all wells in the well bay.			
4	Are you downhole commingling two or more reservoirs?	NO				
5	Will the completed interval be within 500 feet of a lease or unit boundary line? If yes, then comment.	NO				
6	For permanent abandonment, will casings be cut 15 feet below the mudline? If no, then comment.	NO	Final well abandonment will be done at time of platform abandonment.			

Revised Permit to Modify (RPM)

Lease P00166 Area	LA Block 6660 Well Name A030 ST 00 BP 00 Type Development	
Application Status	Approved Operator 01560 Pacific Operators Offshore, LLC	
Questions		
Number Question	Response Response Text	
	oposed operation be NO	
	an EPA Discharge ease provide permit	
	omments for this	
question)		
, ,	ATTACHMENTS	
File Type	File Description	
odf	POOLLC BOP purchase statement	
odf	Current Wellbore Schematic - A-30 Updated Current WD (3-6-2017	
odf	Proposed Wellbore Schematic - A-30 Updated Proposed WD (3-6-20	
odf	A-30 Revised Temp Abandonment program (3-6-2017)	
odf	Proposed Wellbore Schematic	
odf	Current Wellbore Schematic	
odf	A-30 BOP Test Procedures	
odf	A-30 BOP stack	
odf	A-30 CBL 12-31-1968	
odf	A-30 Directional Survey	
odf	A-30 Drilling MW history	
odf	A-30 GL tubing details	
odf	A-30 Geologic Markers	
odf	A-30 IEL 12-28-1968	
odf	A-30 Temporary Abandonmnet Program	
	CONTACTS	
Name	Ronald Nazeley	
Company	Pacific Operators Offshore, LLC	
Phone Number	805-899-3144	
E-mail Address	nazeley@pacops.com	
Contact Description	l control of the cont	

CERTIFICATION: I certify that information submitted is complete and accurate to the best of my knowledge. I understand that making a false statement may subject me to c_1

Name and Title Date
Ronald Nazeley, VP & Chief Engineer 06-MAR-2017

U.S. Department of the Interior Bureau of Safety and Environmental Enforcement (BSEE)

Revised Permit to Modify (RPM)

PAPERWORK REDUCTION ACT OF 1995 (PRA) STATEMENT: The PRA (44 U.S.C. 3501 et seq. Requires us to inform you that we collect this information to obtain knowledge of equipment and procedures to be used in drilling operations. MMS uses the information to evaluate and approve or disapprove the adequacy of the equipment and/or procedures to safely perform the proposed drilling operation. Responses are mandatory (43 U.S.C. 1334). Proprietary data are covered under 30 CFR 250.196. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB Control Number. Public reporting burden for this form is estimated to average 11/4 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to the Information Collection Clearance Officer, Mail Stop 4230, Minerals Management Service, 1849 C Street, N.W., Washington, DC 20240.

Page:

οf