7

of

Page:

Revised Permit to Modify (RPM)

	A Block 6658	8 Well Name A0!	55 ST 01	BP 00 Typ	e Development
Application Status App	proved	Operator 02531 DC	OR, L.L.C.		
Pay.gov	Age	ency		ay.gov	
Amount:	Tra	acking ID:	7	racking ID:	
General Informatio	n				
API 043112017601	Appro	oval Dt 21-NOV-2024	1	Approved B	y Carl Lakner
Submitted Dt 15-NOV-20	24 Well	Status Completed		Water Dept	h 188
Surface Lease P00241	Area	LA		Block	6658
Approval Comments					
Original COA's remain	in force.				
Correction Narrative					
Due to inability to re					
revised with a shallow	w KOP. (**Sid	etrack AST permit	will be rev	ised at a l	ater date)
Wellbore will be fille	ad with camen	+ +o 550: 10-3/4:	CTRD will	he get at A	25 '
Permit Primary Type Ab			CIBP WIII	De set at 4	23 .
Permit Subtype(s)					
Temporary Abandonment	+				
	mpleted Work				
Operation Description					
Procedural Narrative					
Danagan Cummagar: /711	dontha mofor	+~ 02f+ ~i~ 111 t	TD / •		
				wn tree In	stall and test
Skid rig to well A-55				wn tree. In	stall and test
Skid rig to well A-55 BOPE 250/1000psi.	. Check press	ure and bleed down	n. Nipple do		
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP.	. Check press	ure and bleed down $/8$ " tubing to ~ 142	n. Nipple do	14.8ppg Typ	e III abandonmen
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two sta	. Check press RIH with 2-7 ages from 142	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. T	n. Nipple do 20' and lay Cest wellbor	14.8ppg Typ e above the	e III abandonmen cement plug 500
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two sta psi for 15min chartere	. Check press RIH with 2-7 ages from 142 ed. Run 10-3/	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. T 4" scraper to 450f	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Program Summary: (All Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartere 3/8" and 10-3/4" collaunder a separate drill	. Check press RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. T 4" scraper to 450f	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two sta psi for 15min chartere 3/8" and 10-3/4" colla	. Check press RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program.	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. T 4" scraper to 450f	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. Cement plug in two stapsi for 15min chartere 3/8" and 10-3/4" colla	. Check press RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. T 4" scraper to 450f	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartere 3/8" and 10-3/4" colla under a separate drill Subsurface Safety Value	. Check press RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. T 4" scraper to 450f	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. Cement plug in two stapsi for 15min chartere 3/8" and 10-3/4" colla under a separate drill Subsurface Safety Value Type Installed N/	. Check press RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. To 4" scraper to 450f 0-3/4" CIBP at 425	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two states of the state	RIH with 2-7 ages from 142 ed. Run 10-3/ars and set 1 ling program. ve A d Surface Pre	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. The scraper to 4506 0-3/4" CIBP at 425	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartere 3/8" and 10-3/4" colla under a separate drill Subsurface Safety Valuation Type Installed N/ Feet below Mudline Maximum Anticipate Shut-In Tubing Pre	RIH with 2-7 ages from 142 ed. Run 10-3/ars and set 1 ling program. ve A dd Surface Pressure (psi)	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. To 4" scraper to 450f 0-3/4" CIBP at 425	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. Cement plug in two states of the state	RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A ed Surface Pressure (psi) ed Wellhead Pressure	vure and bleed down /8" tubing to ~142 0' to 550'. WOC. To 4" scraper to 4506 0-3/4" CIBP at 425 essure (psi) 350 cessure (psi)	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartere 3/8" and 10-3/4" colla under a separate drill Subsurface Safety Valuation Type Installed N/ Feet below Mudline Maximum Anticipate Shut-In Tubing Pre Maximum Anticipate Shut-In Wellhead P	RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A ed Surface Pressure (psi) ed Wellhead Pressure	vure and bleed down /8" tubing to ~142 0' to 550'. WOC. To 4" scraper to 4506 0-3/4" CIBP at 425 essure (psi) 350 cessure (psi)	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartere 3/8" and 10-3/4" colla under a separate drill Subsurface Safety Valuation Type Installed N/ Feet below Mudline Maximum Anticipate Shut-In Tubing Pre Maximum Anticipate Shut-In Wellhead P	RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A ed Surface Pressure (psi) ed Wellhead Pressure	vure and bleed down /8" tubing to ~142 0' to 550'. WOC. To 4" scraper to 4506 0-3/4" CIBP at 425 essure (psi) 350 cessure (psi)	n. Nipple do 20' and lay Test wellbor tt. RU wirel	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartered 3/8" and 10-3/4" collawater a separate drill Subsurface Safety Value Type Installed N/Feet below Mudline Maximum Anticipate Shut-In Tubing PreMaximum Anticipate Shut-In Wellhead PRig Information Name	RIH with 2-7 ages from 142 ed. Run 10-3/ars and set 1 ling program. Ve A dd Surface Pressure (psi) dd Wellhead Pressure (psi)	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. The scraper to 4506 0-3/4" CIBP at 425 essure (psi) 350 cessure (psi)	n. Nipple do	14.8ppg Typ e above the ine. Run CC	e III abandonmen cement plug 500 L to verify 13-
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartered 3/8" and 10-3/4" collawater a separate drill Subsurface Safety Value Type Installed N/Feet below Mudline Maximum Anticipate Shut-In Tubing PreMaximum Anticipate Shut-In Wellhead PRig Information	RIH with 2-7 ages from 142 ed. Run 10-3/ars and set 1 ling program. Ve A dd Surface Pressure (psi) dd Wellhead Pressure (psi)	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. To 4" scraper to 450f 0-3/4" CIBP at 425 essure (psi) 350 cessure (psi)	n. Nipple do	14.8ppg Type above the ine. Run CC with whipst	e III abandonmen cement plug 500 L to verify 13- ock operations
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartered 3/8" and 10-3/4" collawater a separate drill Subsurface Safety Value Type Installed N/Feet below Mudline Maximum Anticipate Shut-In Tubing PreMaximum Anticipate Shut-In Wellhead PRig Information Name	RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A d Surface Pre ssure (psi) d Wellhead Pr ressure (psi) Id 445	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. The scraper to 4506 0-3/4" CIBP at 425 essure (psi) 350 cessure (psi)	ABS	14.8ppg Type above the ine. Run CC with whipst	e III abandonmen cement plug 500 L to verify 13- ock operations Coast Guard Date
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartered 3/8" and 10-3/4" collar ander a separate drill Subsurface Safety Value Type Installed N/Feet below Mudline Maximum Anticipate Shut-In Tubing Preduction Maximum Anticipate Shut-In Wellhead PRig Information Name DCOR RIG #7	RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A d Surface Pre ssure (psi) d Wellhead Pr ressure (psi) Id 445	ure and bleed down /8" tubing to ~142 0' to 550'. WOC. The scraper to 4506 0-3/4" CIBP at 425 essure (psi) 350 cessure (psi)	ABS	14.8ppg Type above the ine. Run CC with whipst	e III abandonmencement plug 500 L to verify 13- ock operations Coast Guard Date
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. cement plug in two stapsi for 15min chartered 3/8" and 10-3/4" collawater a separate drill Subsurface Safety Value Type Installed N/Feet below Mudline Maximum Anticipate Shut-In Tubing Premaximum Anticipate Shut-In Wellhead PRig Information Name DCOR RIG #7 Blowout Preventers	RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A d Surface Pressure (psi) d Wellhead Pressure (psi) Id 445	wre and bleed down /8" tubing to ~142 0' to 550'. WOC. To 4" scraper to 4506 0-3/4" CIBP at 425 essure (psi) 350 ressure (psi) Type 502 PLATFORM	ABS	14.8ppg Type above the ine. Run CC with whipst Date Pressure	e III abandonmen cement plug 500 L to verify 13- ock operations Coast Guard Date
Skid rig to well A-55 BOPE 250/1000psi. Retrieve 10-3/4" RBP. Dement plug in two states of the p	RIH with 2-7 ages from 142 ed. Run 10-3/ ars and set 1 ling program. ve A ed Surface Pre ssure (psi) ed Wellhead Pr ressure (psi) Id 445	vure and bleed down /8" tubing to ~142 0' to 550'. WOC. To 4" scraper to 4506 0-3/4" CIBP at 425 essure (psi) 350 ressure (psi) Type 502 PLATFORM	ABS Test	14.8ppg Type above the ine. Run CC with whipst Date Pressure High	e III abandonmen cement plug 500 L to verify 13-ock operations

Revised Permit to Modify (RPM)

Lease P00241 Well Name A055 **ST** 01 BP 00 Type Development Area LA **Block** 6658 Application Status Approved Operator 02531 DCOR, L.L.C.

Estimated duration of the operation (days) 3

Verbal	Approval Information						
	Official	Date (mm/	dd/yyyy)				
Questions							
Number	Question	Response	Response Text				
A	Is H2S present in the well? If yes, then comment on the inclusion of a Contingency Plan for this operation.	NO					
В	Is this proposed operation the only lease holding activity for the subject lease? If yes, then comment.	NO					
С	Will all wells in the well bay and related production equipment be shut-in when moving on to or off of an offshore platform, or from well to well on the platform? If not, please explain.	NO	Wells do not required shut-in due to solid steel deck between drill deck and well bay.				
D	If sands are to be commingled for this completion, has approval been obtained?	N/A					
E	Will the completed interval be within 500 feet of a block line? If yes, then comment.	NO					
F	For permanent abandonment, will casings be cut 15 feet below the mudline? If no, then comment.	N/A					
G	Will you ensure well-control fluids, equipment, and operations be designed, utilized, maintained, and/or tested as necessary to control the well in foreseeable conditions and circumstances, including subfreezing conditions?	YES					
Н	Will digital BOP testing be used for this operation? If "yes", state which version in the comment box?	NO					
I	Is this APM being submitted to remediate sustained casing pressure (SCP)? If "yes," please specify annulus in the comment box. If you have been given a departure/denial for SCP, include in the attachments.	NO					

Revised Permit to Modify (RPM)

ease P		ll Name A			O Type Development		
pplica	ation Status Approved Operato	or 02531 DO	COR, L.L.C				
uest:	ions r Question	D	D				
	Are you pulling tubulars and/or	NO Response	Response	Text			
	casing with a crane? If "YES"	110					
	have documentation on how you						
	will verify the load is free per						
	API RP 2D. This documentation						
	must be maintained by the lessee						
	at the lessee's field office.	<u> </u>	1				
K	Will the proposed operation be	NO					
	covered by an EPA Discharge Permit? (Please provide permit						
	number comments for this						
	question).						
L	Will you be using multiple size	NO					
	work string/ tubing/coil						
	tubing/snubbing/wireline? If yes, attach a list of all sizes						
	to be used including the size,						
	weight, and grade.						
M	For both surface and subsea	N/A					
	operations, are you utilizing a						
	dynamically positioned vessel						
	and/or non-bottom supported						
	vessel at any time during this operation?						
		TACHMENT	rs				
ile Ty	ype File Description						
df	Rig/Coil Tubing/Sn	ubbing Uni	t BOP Sch	ematic			
df	Proposed Wellbore Schematic						
odf	Current Wellbore Schematic						
odf	Rig/Coil Tubing/Snubbing Unit BOP Schematic - BOP Verification						
odf	Rig/Coil Tubing/Snubbing Unit BOP Schematic - BOPE Description						
odf	A055 ST01BP00 APM :	A055 ST01BP00 APM Payment Receipt					
odf	A055 ST01BP00 CFR	A055 ST01BP00 CFR 250 1712 Info					
odf		A055 ST01BP00 Directional Survey					
odf	A55 TA Certification	A55 TA Certification by 3rd party REVISED 11/14/2024					
odf	Plt A Well Control	Plt A Well Control Plan					
odf	Well A055 CER						
odf	A55 TA Procedure R	EV F 11/8/	2024				
		CONTACTS					
Name	Vasily Eliseev						
Compan	DCOR, L.L.C.						

803-535-2056

VEliseev@dcorllc.com

Phone Number

E-mail Address

Revised Permit to Modify (RPM)

Lease P002	11 Area	a LA B	lock (6658 Well	Name	A055	ST	01 E	BP 00	Type Development
Applicatio	n Status	Approve	ed	Operator	02531	DCOR,	L.L.C	С.		
Contact De	aarintio	~		C	ONTAC'	m c				
Contact De	scriptio	11		C	ONTAC	15				

CERTIFICATION: I certify that information submitted is complete and accurate to the best of my knowledge. I understand that making a false statement may subject me to complete and accurate to the

Name and Title

Vasily Eliseev, Drilling and Completions Eng

Date

15-NOV-2024

PAPERWORK REDUCTION ACT OF 1995 (PRA) STATEMENT: The PRA (44 U.S.C. 3501 et seq. Requires us to inform you that we collect this information to obtain knowledge of equipment and procedures to be used in drilling operations. MMS uses the information to evaluate and approve or disapprove the adequacy of the equipment and/or procedures to safely perform the proposed drilling operation. Responses are mandatory (43 U.S.C. 1334). Proprietary data are covered under 30 CFR 250.196. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB Control Number. Public reporting burden for this form is estimated to average 11/4 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to the Information Collection Clearance Officer, Mail Stop 4230, Minerals Management Service, 1849 C Street, N.W., Washington, DC 20240.

U.S. Department of the InteriorBureau of Safety and Environmental
Enforcement (BSEE)

BSEE Form BSEE-0123

Revised Permit to Modify (RPM)

Lease P00241 Area LA Block 6658 Well Name A055 ST 01 BP 00 Type Development Application Status Approved Operator 02531 DCOR, L.L.C.

Variances Requested for this Permit

Electronically generated on 11/21/2024 Page 5 of 7

U.S. Department of the InteriorBureau of Safety and Environmental Enforcement (BSEE)

Revised Permit to Modify (RPM)

Lease P00241 Area LA Block 6658 Well Name A055 ST 01 BP 00 Type Development Application Status Approved Operator 02531 DCOR, L.L.C.

Existing Variances

No previously approved variances exist for this permit

U.S. Department of the InteriorBureau of Safety and Environmental Enforcement (BSEE)

Revised Permit to Modify (RPM)

Lease P00241 Area LA Block 6658 Well Name A055 ST 01 BP 00 Type Development Application Status Approved Operator 02531 DCOR, L.L.C.

Reviews

Review: APM - District Production Engineering Review

Sent: 21-NOV-24
Review Started: 21-NOV-24
Review Finished: 21-NOV-24

Info Adequate: Y

Review Remarks:

Review: BOP Control System Drawing Review

Sent: 21-NOV-24
Review Started: 21-NOV-24
Review Finished: 21-NOV-24

Info Adequate: Y

Review Remarks:

Review: Determination of NEPA Adequacy

Sent: 20-NOV-24
Review Started: 20-NOV-24
Review Finished: 20-NOV-24

Info Adequate: Y

Review Remarks:

BSEE Form BSEE-0123 Electronically generated on 11/21/2024 Page 7 of 7