Civil Penalties Program

The goal of the BSEE OCS Civil Penalties Program is to assure safe and clean operations on the OCS. Through the pursuit, assessment, and collection of civil penalties and referrals for the consideration of criminal penalties, the program is designed to encourage compliance with OCS statutes and regulations.

Civil Penalties Summary (as of 2/17/2025)

Penalties Paid for FY2019

(10/1/2018-9/30/2019)

(10/1/2018-9/30/2019)	Wielshies and Data (a)	Domoltes Doid 6	Domilation (a)
Operator Name and Case #	Violation and Date(s)	Penalty Paid &	Regulation(s)
Fieldwood SD Offshore	a 1 11 1	Date Paid \$43,576.00	Violated 30 CFR
LLC LLC	Crane boom collapsed.	443,370.UU	G-110
		December 19, 2018	30 CFR 250.107(a)
G-2016-015			
	Dogombor 1 2015		
	December 1, 2015		
BHP Billiton Petroleum	Rigs top drive traveling assembly	\$38,100.00	G-110
(GOM) Inc.	struck the crown of the derrick.	Manage 11 0010	20 GED 250 107/-)
G-2016-024	March 20, 2016	November 11, 2018	30 CFR 250.107(a)
0 2010 021	1101011 20, 2010		
Fieldwood Energy	Two Shutdown valves (SDV) bypassed	\$120,000.00	(2) P-103
Offshore LLC	on two incoming pipelines.	\$120,000.00	(2) P=103
	, , , , , , , , , , , , , , , , , , ,	December 19, 2018	30 CFR 250.803(c)
G-2016-028	May 20, 2015 - May 21, 2015		
Pacific Operators	A Pacific Operators Offshore, LLC	\$5,513.00	G-110
Offshore, LLC	(POOLLC) employee sustained bodily	\$3,313.00	G-110
	injuries from a fall of	May 14, 2019	30 CFR 250.107(a)
P-2017-002	approximately (18 ft) while		
	installing a temporary catwalk		
	onto the production rig pipe deck.		
	June 27, 2016		
Whistler Energy II,	Falling material in a confined	\$87,152.00	G-110
7117	workspace (Mud/Gas Separator) resulting in a fatality.	August 23, 2019	30 CFR 250.107(a)
G-2017-015			
	March 9, 2016 - March 10, 2016		
Enorgy VVI COM IIC	Failure to maintain accessible	\$31,750.00	G-111
Energy XXI GOM, LLC	evacuation routes and failure to	\$31,/3U.UU	G-111
G-2017-030	provide sufficient barriers to	November 1, 2018	30 CFR 250.107
	out-of-service locations.		
	March 28, 2017		
	March 20, 201/		
Fieldwood SD Offshore	Hotwork being conducted within	\$36,750.00	G-303
LLC	35ft of flammable substances.		
G-2017-038	Tuno 2 2017	December 19, 2018	30 CFR 250.113(a)
	June 2, 2017	\$42 F76 00	0.110
Fieldwood SD Offshore	Flash fire resulted in a person being burned and falling	\$43,576.00	G-110
1110	overboard.	October 22, 2018	30 CFR 250.107
G-2018-007		,	
	August 10, 2017		

		•	
GoMex Energy Offshore, Ltd.	During an inspection, BSEE observed an atmospheric tote tank	\$21,750.00	G-303
G-2018-008	containing a flammable substance located within 35 feet of welding operations, and not rendered inert or protected with flame-proofed covers.	October 18, 2018	30 CFR 250.113(a)
	February 9, 2018		
Arena Offshore, LP	During an inspection, workers initiated an incident that caused	\$16,300.00	G-110
G-2018-010	a release of 1000 psi gas. The workers did not properly plan the job to eliminate hazards.	October 16, 2018	30 CFR 250.107
	February 1, 2018		
Cox Operating, LLC	According to the investigation findings and documents submitted	\$70,749.00	G-303
G-2018-012	to BSEE, a small fire occurred while the workers were performing hot work for the installment of temporary quarters and associated equipment for workover operations.	January 25, 2019	30 CFR 250.113(a)
	February 5, 2018 - February 7, 2018		
ANKOR Energy LLC	Crane lifting operations resulted in an employee hand injury.	\$38,100.00	G-110
G-2018-014	April 12, 2018	November 9, 2018	30 CFR 250.107
Shell Offshore Inc.	During an inspection, BSEE	\$26,750.00	G-110
G-2018-015	discovered an open hole that was not properly barricaded to protect personnel from entering the hazardous area.	October 22, 0218	30 CFR 250.107
	April 20, 2018		
Fieldwood Energy LLC	During a BSEE inspection, the hydraulic control line for the B-	\$26,750.00	P-103
G-2018-022	19 well SCSSV was found tie- wrapped in the closed position, rendering the safety device bypassed, without being flagged or actively monitored. July 25, 2018	April 2, 2019	30 CFR 250.869(a)
Anadarko Petroleum	According to the investigation	\$38,100.00	G-110
Corporation G-2018-023	findings, workers were in the process of removing the rigs Blowout Preventers (BOPs), and High-Pressure Riser System, when	March 7, 2019	30 CFR 250.107
	the Lateral Support Guide frame they were utilizing as a work platform, fell approximately 17 feet, injuring two of the workers. May 19, 2018		
Fieldwood Energy LLC	INC issued due to the improper	\$26,750.00	G-110
G-2018-022	operating, and subsequent exploding, the wells SSV actuator on January 18, 2018.	April 12, 2019	30 CFR 250.107
	January 18, 2018		
	l .	J	1

Shell Offshore Inc.	Incident during well operations resulted in an employee foot	\$43,576.00	G-110
G-2018-026	injury.	March 15, 2019	30 CFR 250.107
	June 25, 2018		
Shell Offshore Inc.	INC was issued due a failure to prevent the discharge of	\$39,000.00	E-100
G-2018-027	hydrocarbons into the Gulf of America.	August 28, 2019	30 CFR 250.107(a)
	May 12, 2016		
Shell Offshore Inc.	Incident - Explosion and a subsequent fire on the platform	\$89,350.00	L-126
G-2019-007	during pig loading operations caused injuries to personnel and	August 15, 2019	30 CFR 250.1000(a)
	>\$25,000 in damage to the facility.		G-110
	November 8, 2017		30 CFR 250.107
	november of zerv		
Walter Oil & Gas Corporation	A pollution event (>50 bbl) occurred during mud transfer	\$75,800.00	G-110
	operations.	June 3, 2019	30 CFR 250.107
	September 3, 2018		E-100
			30 CFR 250.300(a)

19 cases were closed during FY2019 with payments totaling \$913,879.00