Application for Permit to Modify (APM)

Lease P00241 Area LA	Block 6658 Well	L Name B008	ST 01 BP 00	Type Development				
Application Status Appr	oved Operator	02531 DCOR,	L.L.C.					
Pay.gov Amount:	Agency Tracking II): 75630066584	Pay.gov Tracking	ID: 26DUE9RJ				
General Information								
API 043112031101	Approval Dt 0	8-JAN-2019	Approve	e d By John Kaiser				
Submitted Dt 03-JAN-2019	Well Status A	pproved St/Bp	Water D	epth 190				
Surface Lease P00241	Area L	A	Block	6658				

Approval Comments

Conditions of Approval:

- 1) All operations must be conducted in accordance with the OCS Lands Act (OCSLA), the lease terms and stipulations, the regulations of 30 CFR Part 250, Notices to Lessees and Operators (NTLs), the approved (Revised) Application for Permit to Drill (APD/RPD,AST/RST, ABP/RBP), and any written instructions or orders of the District Manager.
- 2) Hold a prespud meeting with the crew to discuss the drilling plan for the well and possible hazards. Hold pit drills and abandon drill prior to spudding.
- 3) A revised PE certification is needed if (1) Casing setting depth or hole interval drilling depth changes by more than 100 ft TVD, (2) the casing/liner equivalent effective test pressure decreases, (3) less cement is to be pumped, (4) more cement is to be pumped in order to isolate a hydrocarbon zone that was not anticipated in the original permit, or (5) a remedial cement job is required that was not included in the original permit. You must have a PE certify these changes prior to these operations being performed. This revised PE certification is needed in a revised permit. For after hour approvals you must submit the revised permit with the PE certification for the revisions to this office within
- 4) All notifications and test results required as per 250.737(d)(2)(ii) must be sent to the Supervisory Inspector and/or the Lead Inspector.
- 5) Casing/liner test pressures are to be adjusted if the actual test fluid weight differs from the approved test fluid weight. Surface Pressures should be adjusted to allow for an equivalent pressure at the appropriate depth. The equivalent test pressure should use the same governing criteria as the original calculation. A revised PE certification is needed if the casing/liner equivalent test pressure decreases.
- 6) High pressure blind shear ram close capability must be available from all BOP control panels. Each BOP control panel must be clearly marked to indicate that the accumulator system high pressure side is required for closing and shearing the drill pipe with the blind-shear rams. If the high pressure bypass selector valve is not available at all BOP control panels then the accumulator system must be set in the high pressure position at all times except for pressure and function testing.
- 7) The test tolerance of the accumulator pump kick on/kick off pressure as well as the low pressure accumulator alarm will be 5%.
- 8) You shall not conduct operations that require the BOP on the well until a revised permit has been approved that includes an independent third party verification stating as per 250.731(c) that (2) The BOP was designed, tested, and maintained to perform under the maximum environmental and operational conditions anticipated to occur at the well; and (3) The accumulator system has sufficient fluid to operate the BOP system without assistance from the charging system.
- 9) In the event of BOP system failure or leak you must immediately contact the District Office and receive approval from the District Manager prior to resuming operations. Be advised that a revised permit will be required to capture 3rd party verification that the BOP is fit for service and will operate in the conditions it which it will be used.

Page:

of

Application for Permit to Modify (APM)

Lease P00241 Area LA Block 6658 Well Name B008 ST 01 BP 00 Type Development

Application Status Approved Operator 02531 DCOR, L.L.C.

- 10) Notify the permitting and compliance sections when the rig is ready for a pre-drill inspection. Please allow adequate time for potential corrective actions prior to planned spud date.
- 11) Notify the permitting section at least 24 hours in advance of starting these approved operations and any subsequent required BOP tests.
- 12) WAR reports are due daily in the eWells system.

Correction Narrative

Permit Primary Type Completion

Permit Subtype(s)

Initial Completion

Describe Operation(S)

Operation Description

Run injection tubing and packer, place well on injection.

Procedural Narrative

See attached Procedure.

Subsurface Safety Valve

Type Installed N/A

Feet below Mudline

Maximum Anticipated Surface Pressure (psi) 480

Shut-In Tubing Pressure (psi)

Rig Information

Name	Id	Туре	ABS Date	Coast Guard Date
DCOR RIG 411	100057	PLATFORM	31-OCT-2020	31-OCT-2020

Blowout Preventers			Test	Pressure
Preventer	Size	Working Pressure	Low	High
Rams	13.625	3000	250	1000
Annular		3000	250	1000

Date Commencing Work (mm/dd/yyyy) 01-FEB-2019

Estimated duration of the operation (days) 30

Verbal Approval Information

Official Date (mm/dd/yyyy)

Questions										
Number	Question	Response	Response	Text						
1	Is H2S present in the well? If yes, then comment on the inclusion of a Contingency Plan for this operation.	NO								
2	Is this proposed operation the only lease holding activity for the subject lease? If yes, then comment.	NO								

οf

Application for Permit to Modify (APM)

Lease PO	0241 Area LA Block 6658 Wel	11 Name BO	008 ST 01 BP 00 Type Development					
Applicat	cion Status Approved Operato	or 02531 DC	COR, L.L.C.					
Questi	ons							
Number	Question	Response	Response Text					
3	Will all wells in the well bay and related production equipment be shut-in when moving on to or off of an offshore platform, or from well to well on the platform? If not, please explain.	NO	SOLID STEEL DECK BETWEEN DRILL DECK AND WELL BAY, PER FIELD RULES.					
4	Are you downhole commingling two or more reservoirs?	N/A						
5	Will the completed interval be within 500 feet of a lease or unit boundary line? If yes, then comment.	NO						
6	For permanent abandonment, will casings be cut 15 feet below the mudline? If no, then comment.	N/A						
7	Will the proposed operation be covered by an EPA Discharge Permit? (Please provide permit number in comments for this	NO						
	question)	⊥ FTACHMENT	rs					
File Typ		i incimini						
pdf	Rig/Coil Tubing/Sn	ubbing Uni	t BOP Schematic					
pdf	Proposed Wellbore	Schematic						
pdf	Current Wellbore S	chematic						
pdf	B8 ST01 Procedure							
pdf	B8 ST01 Well Contr	ol Plan						
pdf	B8 ST01 Wellhead S	ystem						
pdf	B8 ST01 APM Receip	t						
pdf	APM B8 ST01 Public	Informati	on					
		CONTACTS						
Name	Jimilyn Summers							
Company	DCOR, L.L.C.							
Phone N								
E-mail .	Address jsummers@dcorllc.c	om						
Contact	Description							
	Tynan bradley							
DCOR, L.L.C.								
	805-535-2026							
	tbradley@dcorllc.c	om						
	David Cohen							

Page:

of

OMB Control Number 1014-0026 OMB Approval Expires 05/31/2017

Application for Permit to Modify (APM)

Lease	P00241	Area	LA B	lock	6658	Well	Name	в008	ST 01	BP	00	Type Development
Appli	cation	Status	Approve	ed	Ope	erator	02531	DCOR,	L.L.C.			
CONTACTS												
	DCOR, L.L.C.											
	805-535-2028											
			dad	ohen@	dcorllo	c.com						

CERTIFICATION: I certify that information submitted is complete and accurate to the best of my knowledge. I understand that making a false statement may subject me to complete and accurate to the

Name and Title Date limilyn Summers, Well Operations Technicia 03-JAN-2019

PAPERWORK REDUCTION ACT OF 1995 (PRA) STATEMENT: The PRA (44 U.S.C. 3501 et seq. Requires us to inform you that we collect this information to obtain knowledge of equipment and procedures to be used in drilling operations. MMS uses the information to evaluate and approve or disapprove the adequacy of the equipment and/or procedures to safely perform the proposed drilling operation. Responses are mandatory (43 U.S.C. 1334). Proprietary data are covered under 30 CFR 250.196. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB Control Number. Public reporting burden for this form is estimated to average 11/4 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to the Information Collection Clearance Officer, Mail Stop 4230, Minerals Management Service, 1849 C Street, N.W., Washington, DC 20240.

Page:

of